

- ✓ : Compatible
- ? : To be checked
- X : Not compatible

Last update: 29.03.2017

		3-wire kit	Spyder LM	Cobra AC	profilo LM AC	profilo WL AC	profilo harness AC	profilo RCU AC	Serenity DPC AC	primero DPC AC	Type of micro
TETRA / TETRAPOL RADIO											
115-1177	Motorola MTP 700 MTP 750	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1179	Motorola TCR 1000	X	X	X	X	X	X	✓	X	X	---
115-1190	Motorola MTP 850S, MTP6550, DMR	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1926	Motorola MTP 850	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1939	Motorola MTH 800 MTH 650	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-3009	Motorola MTP 3000 MTP3100, MTP3200, MTP3250	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1218	EADS THR 880i	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-0028	EADS THR 9	?	?	✓	✓	✓	✓	X	✓	✓	mm6
115-1189	EADS TPH 700	✓	?	✓	✓	✓	✓	X	✓	✓	mm7
115-1254	RUAG COVERT 700	?	?	✓	✓	✓	✓	X	✓	✓	
115-0063	EADS THR8, TH1n	?	?	✓	✓	✓	✓	X	✓	✓	?
115-1118	Matra SG 2	✓	✓	✓	✓	✓	✓	X	✓	X	mm7
115-0935	Sepura STP 8000	✓	✓	✓	✓	✓	✓	✓	✓	✓	mm6
115-1141	Sepura SRP/SRH/SRC series SRP2000, SRC3000, SRC3300, SRH3500, SRH3800, SRH3900	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-3023	Airbus TPH900	✓	✓	✓	✓	✓	✓	X	✓	✓	mm7
MOTOROLA											
115-1102	Motorola GP 300 GP68, GP88, GP300, GP308, GP2000, GP3188, PRO3150, CP040, P080, CT250, CT450, GTX, SP50, P110, P1225, LTS2000, CP150, CP200	✓	✓	X	X	X	X	X	X	X	mm6
115-1121	Motorola GP 340 GP240, GP280, GP330, GP340, GP360, GP380, GP640, GP680, GP1280, GP140, GP320, GP328, GP338, GP329, GP339, HT750, HT1250LS, HT1550XLS, MTX850LS, MTX8250LS, MTX900, MTX950, MTX960, MTX9250, PTX700, PTX760, PTX780, PRO5150, PRO5350, PRO5450, PRO5550, PRO5750, PRO150, PRO7350, PRO7450, PRO7550, PRO7750, PRO9150, ATS 2500	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1122	Motorola GP 344 EX500, EX600, GP328plus, GP338plus, PRO5150elite, GP344, GP388, GL2000	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1132	Motorola GP 900 GP900, HT1000, MTX1000, XTS3000/Astro, XTS2250, XTS2500, XTS3500, XTS5000, MT2000, MTS2000, MTS2010, MTX8000, MTX838, MTX9000, JT1000	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1190	Motorola MTP 850S, DMR DP 3400/3401, DP 3600/3601, DP4400, DP4401, DP4600, DP4601, DP4800, DP4801, APX3000, APX6000, APX7000, XPR6550, P8260, P8268, P8200, P8208	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-3009	Motorola DP2000/3000 DP2400, DP2600, DP3441	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
ICOM											
115-1124	Icom IC-F3 / 90° (2.5/3.5) IC-02E, M12, IC-F3, IC-F34, IC-F3s, IC-F4, IC-F4s, IC-F25SR, IC- F34GS, IC-H2, IC-H6, IC H12, IC-J12, IC-M5, IC-U12, IC-U16, IC- A2, IC-A20, IC-A21, IC-A22f, IC-F3102D, IC-F3022, IC-F4102D, IC- F4022, IC-F4029	✓	✓	X	X	X	X	X	X	X	mm6
115-1127	Icom IC-F31 / 9 pin IC-F31GS, IC-F40, IC-F41GT, IC-F40GS, IC-F51, IC-F61, IC- F3062, IC-F3161, IC-F4062, IC-F4161, IC-F50, IC-F60	✓	?	✓	✓	✓	✓	X	✓	✓	mm7
KENWOOD											
115-1916	Kenwood TK 208 (2.5/3.5) TH-22, TH-25, TK-220, TK-320, TK-240, TK-340, TK-240D, TK- 340D, TK-208, TK-308, TK-430, TK-431, TK-250, TK-350, TK-353, TK-260, TK-270, TK-260G, TK-360G, TK-360, TK-370, TK-270G, TK-370G, TK-248, TK-348, TK-2000, TK-2107, TK-3107, TK-2100, TK-3100 Pro-Talk, TK-3101 Free Talk XL, TK-2102, TK-3102 Pro- Power, TK-2160, TK-3160, TK-2170, TK-3000, TK-3170, TK-2360, TK-3201, TK-2302, TK-3302, TK-2300, TK-3300, TK-3301, TK- 2306, TK-3306, TK-3360E, TK-3400	✓	✓	X	X	X	X	X	X	X	mm6
115-1916	NX-220, NX-320	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1123	Kenwood TK 280 (Multi-pin) TK-380, TK-390, TK-480, TK-481, TK-2140, TK-3140, TK-2180, TK- 3180, NEXEDGE NX-200, NX-210, NX-300 Exceptions: TK-280/290/290-11B needs modifications (Vin Direct connection)	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6

YAESU VERTEX											
115-1184	Yaesu Vertex VX-800 VX-600, VX-800, VX-900, MH-360, MH-450	?	?	X	X	X	X	X	X	X	mm7
115-1185	Yaesu Vertex VX-820 VX-P820 VX-700, VX-821, VX-824, VX-829, VX-920, VX-921, VX-581	✓	?	X	X	X	X	X	X	X	mm7
Hytera											
115-1249	X1e	?	?	✓	✓	✓	✓	X	✓	✓	?
115-1122	TC-780U	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-3013	Hytera PT580X-PD78X/G PT580, PT580H, PD70X, PD70XG, PD78X, PD78XG, PD88XT	✓	✓	✓	✓	✓	✓	X	✓	✓	mm7
VARIOUS											
115-1108	Hirose HRS 6 pin Astro Digital Saber, Expo, MX1000, Tait TP9100 <i>Side connector to HRS => Adapter without electronic, pinning must be checked</i>	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1109	Hirose HRS 12 pin Astro Digital Saber, MX100, MX 3010 <i>Side connector to HRS => Adapter without electronic, pinning must be checked</i>	✓	✓	✓	✓	✓	✓	X	✓	✓	mm6
115-1192	Harris RF-5800 / Thales MBITR	X	X	✓	✓	✓	✓	X	✓	✓	?
115-0018	Harris RF-7800	?	?	✓	✓	✓	✓	X	✓	✓	mm6
115-1182	Bosch FUG 10 FUG 11B	✓	✓	✓	✓	✓	✓	X	✓	✓	mm7
115-1250	Entel HT 2.0 Spiralkabel HT723	?	?	✓	✓	✓	✓	X	✓	✓	?
115-1178	Tait TP 9107	?	?	✓	✓	✓	✓	X	?	?	mm6
115-0935	SBP8000, SCP8000 (Sepura DMR radio)	✓	✓	X	X	X	X	X	X	X	mm6